

Dust Collector Maintenance Contract

Contracts available for Camfil and non-Camfil dust collection systems

Camfil APC extends the unprecedented peace of mind that comes with owning and operating a Camfil APC Dust Collector with our preventative maintenance program. We extend this service to non-Camfil systems as well. Camfil APC provides a continuing service schedule that can be customized to fit any application.

Pricing available for 1, 2, or 4 service visits per year with one filter changeout included. Maintenance contracts do not include replacement filter costs or filter disposal.

The Service Specialist will check the system for signs of moisture and foreign material. System balance, air flow readings, and leak trace test may be performed if necessary.



SYSTEM AND PERFORMANCE CHECKS

CLEANING SYSTEM:

- Solenoids
- Diaphragm valves
- Controller settings and operation
- Electrical settings

- Air pressure settings
- Filter regulator cleanout
- Airline leakage
- Differential pressure numeric
- Air header tank moisture check
- Compressed air connections
 - Pulse pipe alignment

BIN - VENT HOUSING:

- Abrasion issues
- Hardware and seam welds
- All caulk seals on housing
- Door gaskets
- Check clean air plenum for dust
- Cam bar operation
- Cam bar attachment brackets
- Sprinkler system leaks

- Clean spark baffles and inlet baffles
- X-vent seals and perforations
- Blower to Bin-Vent connection
- Blower amp draw
- Inspect blower operation for vibration
- Grease bearings on blower
- Drive belts
- View ports

- Magnahelic gauge reading on after filter side
- Inspect door latch bracketry and hardware
- View filters for abrasion or manufacturing issues
- Inlet connections and cleanliness

HOPPER AND SUPPORT MODULE:

- Hopper to Bin-Vent connection
- Hopper cleaning
- View ports
- Airlock Service

- Butterfly valve
- Slide gate
- Drum cover kit
- Support hardware

- Level indicator
- Drawer configuration if applicable
- Platform attachment hardware and bracketry

INFEED DUCT:

Dust accumulation



Leakage



Cleaning



Camfil APC • 3505 South Airport Road, Jonesboro, AR 72401 • 870-933-8048 • e-mail: filterman@camfil.com • 800-479-6801